


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	08/20/2012	1757		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #7	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	08/20/2012 0700
	Position:	Operations Section Chief	To:	08/20/2012 1744
7. Personnel Roster Assigned				
Name	ICS Position	DUTY CELL		
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Marcus Muccianti	SOTF#7			
8. Activity Log				
Activity Area	Downstream of Morrow Lake Dam	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	47			
Total Boom Deployed	NA			
Activity	<u>START SOTF Team # 2 Activity:</u> Team SOTF #7 launched from Parcom Street cul-de-sac in Kalamazoo and conducted poling ops. A total of 47 poling locations were assessed at downstream of Morrow Lake Dam. <u>Poling</u> <ul style="list-style-type: none"> • Morrow Lake Dam Poling: <ul style="list-style-type: none"> ○ Poled 21 points at MP 40.30 <ul style="list-style-type: none"> ▪ 21 none, 0 light, 0 moderate, 0 heavy ○ Poled 7 points at MP 40.90 <ul style="list-style-type: none"> ▪ 7 none, 0 light, 0 moderate, 0 heavy ○ Poled 19 points at MP 41.10 <ul style="list-style-type: none"> ▪ 19 none, 0 light, 0 moderate, 0 heavy All locations passed the temperature requirement.			
Health and Safety Issues	None			
Comments	Notes are in Logbook SOFT 7.			

